

**Annex I**

Quantities of APIs in random batch inspection	One piece is to be randomly inspected when the total number of pieces is within 50; two when it is between 51 and 100; three when it is between 101 and 500; four when it is between 501 and 1000; and five when it is more than 1,000.
---	---